

1/53 Replacement Sheet(s)





2/53 Replacement Sheet(s)

FIG.2





3/53 Replacement Sheet(s)





FIG.4 66--70 68-77 76-74 -83 -81 81--78 80--82 -84 72 821




4/53 Replacement Sheet(s)

 $FIG.4(\alpha)$





5/53 Replacement Sheet(s)









FIG.6





7/53 Replacement Sheet(s)

FIG.7




FIG.8




FIG.9







FIG. 10



9/53 Replacement Sheet(s)






FIG. 12α




FIG. 12b







FIG. 13

11/53 Replacement Sheet(s)



12/53 Replacement Sheet(s)




FIG. 14



13/53 Replacement Sheet(s)

FIG. 15

950

952

954


956

5kΩ

958

960


962






14/53 Replacement Sheet(s)


FIG. 16b







15/53 Replacement Sheet(s)














16/53 Replacement Sheet(s)


FIG. 18



 $FIG.19(\alpha)$











17/53 Replacement Sheet(s)



18/53 Replacement Sheet(s)





19/53 Replacement Sheet(s)





FIG. 19g





 $FIG.20(\alpha)$






FIG.20(b)







21/53 Replacement Sheet(s)

FIG.21




FIG.22







FIG.23



PEAK DETECTOR 349

PEAK DETECTOR 349

PEAK DETECTOR



23/53 Replacement Sheet(s)




FIG.25



24/53 Replacement Sheet(s)

FIG.26b FIG.26a٧٩d V_{dd} 664 664 POWER DOWN POWER DOWN -660 660 662-667 612 662-INPUT INPUT -666 658 658





FIG. 28

674
676
678
680
Vp1
Vp2
Vp3
Vp4
682
686
688
688





25/53 Replacement Sheet(s)





26/53 Replacement Sheet(s)






00




28/53 Replacement Sheet(s)







29/53 Replacement Sheet(s)






30/53 Replacement Sheet(s)











32/53 Replacement Sheet(s)






33/53 Replacement Sheet(s)






34/53 Replacement Sheet(s)






35/53 Replacement Sheet(s)






36/53 Replacement Sheet(s)






37/53 Replacement Sheet(s)






38/53 Replacement Sheet(s)

FIG. 31 α FIG. 31 α 868
876 666 666 61







39/53 Replacement Sheet(s)

FIG.33b




FIG.34








FIG.35



41/53 Replacement Sheet(s)






FIG.37a






FIG.37b






43/53
Replacement
Sheet(s)


FIG.38






44/53 Replacement Sheet(s)









45/53 Replacement Sheet(s)








46/53 Replacement Sheet(s)







858 BIAS 862 CAP 2




47/53 Replacement Sheet(s)








48/53 Replacement Sheet(s)






49/53 Replacement Sheet(s)






50/53 Replacement Sheet(s)






51/53 Replacement Sheet(s)





52/53 Replacement Sheet(s)



53/53 Replacement Sheet(s)

